Structure Design Staff Meeting Thursday, January 15, 2009 Conference Room C 10:00 AM

1.	•	nneld to smoke in designated areas.	Darlene
	W2 statements will be generated from the BEACON system and will be mailed directly to the employee's home address as listed in the BEACON system. Check in ESS to make sure your address is correct.		
	Rollover vacation was converted to sick leave on December 31 st for those who had over 240 hours. Quota balances should be correct. Working on the time statement again – may be completed by March.		
	All employees with secondary employment must fill out Secondary Employment Forms – they are due now.		
2.	Form Letters/Signature		
	Memos		
	Michios		Letters
	FROM:	<u>for</u> G. R. Perfetti <u>(your name)</u>	Letters Sincerely,
		<u>for</u> G. R. Perfetti <u>(your name)</u>	
		<u>for</u> G. R. Perfetti <u>(your name)</u>	Sincerely,
3.	FROM: PC/CADD U Bob Wright i		Sincerely, Your name for G. R. Perfetti, P.E. Bob
 4. 	FROM: PC/CADD U Bob Wright is on all computed on the computed of the computed	pdatess updating work stations for STAAD as peoters is continuously being added.	Sincerely, Your name for G. R. Perfetti, P.E. Bob ple finish class. New inventory Greg
	FROM: PC/CADD U Bob Wright is on all computed on the computed of the computed	pdatess updating work stations for STAAD as peoters is continuously being added.	Sincerely, Your name for G. R. Perfetti, P.E. Bob ple finish class. New inventory Greg

DOT and State finances are poor – out of money by June 2009. At that point the DOT's balance will have dropped to 170 million, which is DOT's lowest allowable reserve. To keep up with cashflow, Project revenues are updated every month. Gas tax (55-60%), DMV fees (10-15%) Road user fees – all have significantly plummeted. In the case of DMV fees, it is due to the closing of several loop holes for licenses and registrations for out of state vehicle owners.

Shortfall in the State and Federal funds – prediction that it will take 3 years to climb out of budget hole. Anticipated 15 million a month lettings for next 12 months. Projects keep getting pushed out. Managers must still go by Let List with all Projects – projects not let each month will become 'shelf' projects, able to be pulled off the shelf and let as money becomes available.

It is anticipated that NC might get 2 billion from the Federal Government's stimulus plan. To be ready for stimulus money, Divisions have been asked for priority list of projects to be let POC by Divisions – asked for variety of project type(e.g. bridge replacement, new construction, paving, grading, etc) so as not to let too much of one type of project and drive up the cost of the projects.

Retiree Temporary workers are gone – no mention about other temporary workers.

Greg needs some sort of data to carry to Art – Unit wide not coming close on meeting PDA requirements.

- 7. Legal Loads.....Brian

LRFR training:

When using the Standard Rating sheets: For equal spans – just show '1', '2', '3' (i.e., numbers corresponding to Controlling Load Rating) in one span – don't repeat each span.

Dan Holderman raised concerns about designing right to the limit – should be designing for slightly over-capacity. For 0'to 75' span lengths – HL93 doesn't control over all legal trucks. There is a new standard sheet for LRFR rating. Greg asked people to keep track and report what extra detailing is required to meet the 1.1 rating for spans \leq 60'.

Prestressed girder program has been updated to reflect the entered ADTT. ADTT on the form is directional not total.

for certain cases.

Cored slab standard bridges: pilot project by Laura Sutton—two bridges. Plan assembly manner—use standard 'models', which are pre-engineered to only need plan assembly. Cored slab standards can be used for FSM projects.

to maintain 4% grade (maximum) and 60° skew (maximum) for all cored slabs, except

Budget based projects – still being looked into as a possibility by upper Management. This is a Program for reducing <u>engineering</u> costs, especially for small projects.

Foundation sketches and whether vertical clearance is adequate are main issues that need to be met. Discussed use of old style foundation request drawing. Need to work toward a more timely completion of preliminary designs and preliminary general drawings.